



## PlantWATCH Manual

# Updating Software to Newer Version

From time to time, as enhancements are made and bugs are fixed, you will need to either update or reinstall Riotech's VTU1X Configuration software. Please RioTech Instruments for information on what software versions need a complete reinstallation.

Updates are only important when you have been notified of an upgrade that fixes a bug or problem.

Updating the software:

To update, users only need to copy and replace the PlantWATCH.exe file. The size of this file is usually 10-13 Mbytes

To see if there has been an update check the version number found when you run the 1X configuration software under the about menu against the version on the Riotech Instrument web site at [www.riotechinst.com](http://www.riotechinst.com).

Just scroll down to the bottom and click on Software Downloads.

[NEXT](#)




Next navigate within the Windows File Explorer, go to the C: drive and locate the “RioTech” folder. Within this folder will be the software application files. Replace the existing “VTU1X Configuration.exe” file with the newer version.

After this copy and replace, the update is finished. Just run the program

The software program, “VTU1X Configuration.exe” should be under this drive and folder



To update the software, just paste the VTU1X Configuration.exe into the RioTech directory



File Name	Modified	Type	Size
VTU1X Configurator.aliases	3/8/2016 2:30 PM	ALIASES File	1 KB
VTU1X Configurator.exe	3/8/2016 2:30 PM	Application	4,610 KB
VTU1X Configurator.ini	3/8/2016 2:30 PM	Configuration sett...	1 KB

**END**